



AbrasiMet® XL Pro Service Plans



Protect Your Investment

Labs run more efficiently and consistently with well-maintained equipment.



Reduce Unplanned Downtime

Regular equipment maintenance will reduce the hassle of unexpected downtime and associated costs.



Ensure Consistent Results

Confidently analyze lab results with the equipment maintained by the trusted experts at Buehler.



Preventative Maintenance

Protect your investment and ensure consistent performance, minimize downtime and reduce the costly repairs with Buehler Preventative Maintenance and Calibration Services.

Preventative Maintenance Service Plan Ensures Consistent and Reliable Results

- Annual visit includes Wear Parts Kit and 20 Point Maintenance Check list
- Trained technicians able to perform Preventative Maintenance on multiple machines in one visit
- Unlimited Phone Support
- 10% Replacement Part Discount





Maintenance Checklist

Our comprehensive 20 point maintenance checklist is thorough, ensuring the AbrasiMet XL Pro is running efficiently.

20 Point Maintenance Checklist

- Inspect spindle assembly for excessive play.
- Check coolant tank for proper docking.
- Check door lock assembly for correct operation.
- Ensure quick lock nut for proper operation.
- Inspection cutting bay LED's.
- Check all coolant lines for leaks and clogging.
- Check X,Y & Z axis operation for smooth travel and clean if necessary.
- Clean and lubricate X-axis lead screw. Check for irregularities.
- Check front panel joystick for proper function
- Document firmware/software versions and operational hours
- Check for proper coolant flow.
- Check wash down hose for proper flow.
- Inspect electrical compartment for contamination.
- Clean filter screen and coolant tank.
- Clean inside the cutting bay, bed and rails.
- Inspect cutting bay windows for damage and leaks.
- Verify limit switches are working correctly.
- Inspect belts and pulleys for proper tension and wear.
- Inspect rubber boot for wear or cracks.
- Verify mist-extractor is properly ventilating . (if applied)




Wear Parts Kit

The parts listed below are included with every Preventative Maintenance visit

AbrasiMet XL Pro Wear Parts - 102320SRV

Includes

- Timing Belts
- Quick Locking Nut
- Linear Bearings
- Coolant Hose
- Shaft Coupling
- Actuator Bellows



BUEHLER Worldwide Headquarters
North America-South America Offices
41 Waukegan Road
Lake Bluff, Illinois 60044-1699 USA
P: 800 BUEHLER (800-283-4537)
P: (847) 295-6500
www.buehler.com | info@buehler.com

European Headquarters
BUEHLER Germany
info.eu@buehler.com

BUEHLER France
info.eu@buehler.com

BUEHLER United Kingdom
info.eu@buehler.com

BUEHLER China
info.cn@buehler.com

BUEHLER Japan
info.japan@buehler.com

BUEHLER Asia-Pacific
info.asia@buehler.com