



AbrasiMet™ 250 Service Plan



Protect Your Investment

Labs run more efficiently and consistently with well-maintained equipment.



Reduce Unplanned Downtime

Regular equipment maintenance will reduce the hassle of unexpected downtime and associated costs.



Ensure Consistent Results

Confidently analyze lab results with the equipment maintained by the trusted experts at Buehler.




Preventative Maintenance

Protect your investment and ensure consistent performance, minimize downtime and reduce the costly repairs with Buehler Preventative Maintenance and Calibration Services.

Preventative Maintenance Service Plan Ensures Consistent and Reliable Results

- Annual visit includes Wear Parts Kit and 12 Point Maintenance Check list
- Trained technicians able to perform Preventative Maintenance on multiple machines in one visit
- Unlimited Phone Support





Maintenance Checklist

Our comprehensive 12 point maintenance checklist is thorough, ensuring the AbrasiMet 250 is running efficiently.

12 Point Maintenance Checklist

- | | |
|---|--|
| <input checked="" type="checkbox"/> Clean cutting bay | <input checked="" type="checkbox"/> Check safety hood lock for proper function |
| <input checked="" type="checkbox"/> Check and inspect coolant lines | <input checked="" type="checkbox"/> Check light assembly, clean if necessary |
| <input checked="" type="checkbox"/> Verify motor and pump for proper rotation | <input checked="" type="checkbox"/> Verify internal components are in operational condition |
| <input checked="" type="checkbox"/> Check hood and window integrity | <input checked="" type="checkbox"/> Check overload for proper amperage setting |
| <input checked="" type="checkbox"/> Check and clean coolant tank for fluid level and abrasive buildup | <input checked="" type="checkbox"/> Check for correct cutting lever tension, adjust if necessary |
| <input checked="" type="checkbox"/> Check vises for proper function | <input checked="" type="checkbox"/> Perform and inspect a cut test for functional operation |



Wear Parts Kit

The parts listed below are included with every Preventative Maintenance visit

AbrasiMet 250 Wear Parts Kit 10101SRV

Includes

Motor Cable	Coolant
Spark Pad	Chamber Strip Lighting
Hood Gas Spring	Chamber Spot Lighting



BUEHLER Worldwide Headquarters
North America-South America Offices
41 Waukegan Road
Lake Bluff, Illinois 60044-1699 USA
P: 800 BUEHLER (800-283-4537)
P: (847) 295-6500
www.buehler.com | info@buehler.com

European Headquarters
BUEHLER Germany
info.eu@buehler.com

BUEHLER France
info.eu@buehler.com

BUEHLER United Kingdom
info.eu@buehler.com

BUEHLER China
info.cn@buehler.com

BUEHLER Japan
info.japan@buehler.com

BUEHLER Asia-Pacific
info.asia@buehler.com